


Hunters Point 6-29-16 Site Visit

Hunters Point 6-29-16 Site Visit


Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0200.JPG
Date Time Stamp	6/29/2016 11:06:53 AM
Description	Hunters Point Base Realignment Area Map with green markings from Anthony Smith
Photographer	



Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0201.JPG
Date Time Stamp	6/29/2016 11:16:25 AM
Description	Background soil location on the north side of the Spear and Fisher intersection (as per Anthony Smith)
Photographer	




Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0202.JPG
Date Time Stamp	6/29/2016 11:16:42 AM
Description	Overview of background soil location on the north side of the Spear and Fisher intersection
Photographer	



Hunters Point 6-29-16 Site Visit


Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0203.JPG
Date Time Stamp	6/29/2016 11:20:00 AM
Description	Secondary background location with native serpentine soils, west of the first background site and on the north side of Spear Avenue
Photographer	[REDACTED]

DSCN0203.JPG



Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0204.JPG
Date Time Stamp	6/29/2016 11:24:05 AM
Description	Building 351A on Cochrane Street, covered crawl space access at west corner of building
Photographer	[REDACTED]

DSCN0204.JPG



Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0205.JPG
Date Time Stamp	6/29/2016 11:25:28 AM
Description	Building 351A, looking into the crawl space access at west corner of building
Photographer	[REDACTED]

DSCN0205.JPG



Hunters Point 6-29-16 Site Visit

Attributes

Subject	Hunters Point Site Visit
File Name	DSCN0206.JPG
Date Time Stamp	6/29/2016 11:26:19 AM
Description	Looking into the boarded up building 351A
Photographer	[REDACTED]

DSCN0206.JPG



Attributes

Subject	Hunters Point Site Visit
File Name	DSCN0207.JPG
Date Time Stamp	6/29/2016 11:27:12 AM
Description	Building 351A, looking into the second crawl space access location
Photographer	[REDACTED]

DSCN0207.JPG



Attributes

Subject	Hunters Point Site Visit
File Name	DSCN0208.JPG
Date Time Stamp	6/29/2016 11:27:34 AM
Description	Building 351A, looking into the second crawl space access location
Photographer	[REDACTED]

DSCN0208.JPG



Hunters Point 6-29-16 Site Visit

Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0209.JPG
Date Time Stamp	6/29/2016 11:27:57 AM
Description	Second crawl space access location for building 351A
Photographer	

DSCN0209.JPG



Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0210.JPG
Date Time Stamp	6/29/2016 11:36:47 AM
Description	Looking west over the fenced 707 triangle
Photographer	

DSCN0210.JPG



Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0212.JPG
Date Time Stamp	6/29/2016 11:37:32 AM
Description	Fenceline of the 707 triangle
Photographer	

DSCN0212.JPG



Hunters Point 6-29-16 Site Visit

Attributes

Subject	Hunters Point Site Visit
File Name	DSCN0213.JPG
Date Time Stamp	6/29/2016 11:41:40 AM
Description	Looking northeast at the palm trees and the crane structure in the background
Photographer	

DSCN0213.JPG



Attributes

Subject	Hunters Point Site Visit
File Name	DSCN0214.JPG
Date Time Stamp	6/29/2016 11:44:42 AM
Description	Looking north at the two palm trees over the theater foundation
Photographer	


DSCN0214.JPG



Attributes

Subject	Hunters Point Site Visit
File Name	DSCN0216.JPG
Date Time Stamp	6/29/2016 11:48:15 AM
Description	Brown soil collection location next the west palm tree (as per Anthony Smith)
Photographer	

DSCN0216.JPG



Hunters Point 6-29-16 Site Visit

Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0217.JPG
Date Time Stamp	6/29/2016 11:50:14 AM
Description	Second soil collection location next the west palm tree, on the west side (as per [REDACTED])
Photographer	[REDACTED]

DSCN0217.JPG



Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0218.JPG
Date Time Stamp	6/29/2016 11:52:38 AM
Description	Looking northeast over the theater foundation
Photographer	[REDACTED]

DSCN0218.JPG



Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0219.JPG
Date Time Stamp	6/29/2016 11:53:33 AM
Description	Back corner of theater foundation, ladder drop location to get more background soil (as per [REDACTED])
Photographer	[REDACTED]

DSCN0219.JPG



Hunters Point 6-29-16 Site Visit

Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0220.JPG
Date Time Stamp	6/29/2016 11:56:23 AM
Description	Back corner of theater foundation, ladder drop location to get more background soil (as per [REDACTED])
Photographer	[REDACTED]

DSCN0220.JPG



Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0221.JPG
Date Time Stamp	6/29/2016 12:04:56 PM
Description	Red brick building where other people would get background soil samples [REDACTED]
Photographer	[REDACTED]

DSCN0221.JPG



Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0222.JPG
Date Time Stamp	6/29/2016 12:06:46 PM
Description	Red brick building where other people would get background soil samples [REDACTED]
Photographer	[REDACTED]

DSCN0222.JPG



Hunters Point 6-29-16 Site Visit

Attributes

Subject	Hunters Point Site Visit
File Name	DSCN0223.JPG
Date Time Stamp	6/29/2016 12:16:13 PM
Description	Facing northeast from the base of the north pier
Photographer	[REDACTED]


DSCN0223.JPG



Attributes

Subject	Hunters Point Site Visit
File Name	DSCN0224.JPG
Date Time Stamp	6/29/2016 12:16:18 PM
Description	Facing east from the base of the north pier
Photographer	[REDACTED]


DSCN0224.JPG



Attributes

Subject	Hunters Point Site Visit
File Name	DSCN0225.JPG
Date Time Stamp	6/29/2016 12:16:50 PM
Description	Facing south from the base of the north pier
Photographer	[REDACTED]

DSCN0225.JPG



Hunters Point 6-29-16 Site Visit

Attributes	
Subject	Hunters Point Site Visit
File Name	DSCN0227.JPG
Date Time Stamp	6/29/2016 12:19:53 PM
Description	Facing northeast from the base of the north pier, zoomed in on buildings 253 and 211
Photographer	

DSCN0227.JPG

